





SS Customs Inc 1500 Industrial Way Redwood City, CA 94063 US

Invoice

+1 6505627034 sales@sscamerica.com www.sscamerica.com

Ryan	Tu		

 INVOICE
 DATE
 TOTAL DUE
 TERMS
 ENCLOSED

 4734
 05/18/2021
 \$0.00
 Due on receipt

VEHICLE 1989 Land Cruiser

SALES REP Tanya

ACTIVITY in complete on	QTY-	RATE	AMOUNT
Installations and Labor:Window Tint SUV (Ceramic) Solar Gard Vortex IR Ceramic tint film blocks up to 70% of solar heat for a cooler ride, and UV protection equivalent to SPF 285. Helps protect your sts and dash from harmful UV light and an additional layer of security from the first t	1	775.00	775.00
This service includes window tinting of the sides and back gram added tint for the full rear window. Percentages: 70% uniform			
Installations and Labor:Window Tint SUV (Ceramic) Solar Gard Vortex IR Ceramic tint film blocks up to 70% of solar heat for a cooler ride, and UV protection equivalent to SPF 285. Helps protect your seats and dash from harmful UV light and an additional layer of security from smash and grab theft.	1	395.00	395.00
This service includes window tinting of the sides and back glass with added tint for the full rear window. Percentages: 70%			

INITIALS:





SS Customs Inc 1500 Industrial Way Redwood City, CA 94063 US +1 6505627034 sales@sscamerica.com www.sscamerica.com

BILL TO	STEEL SECRETARIES A	NOTES SEE	25,9402	September 1	5000	BASE.
Ryan	Iu					

INVOICE#	DATE	TOTAL DUE		TERMS	ENCLOSED
4734	05/18/2021	\$585.00	200	Due on receipt	

VEHICLE

1989 Land Cruiser

SALES REP

Tanya

ACTIVITY THE PROPERTY OF THE P	QTY	RATE	AMOUNT
Installations and Labor:Window Tint SUV (Ceramic) Solar Gard Vortex IR Ceramic tint film blocks up to 70% of solar heat for a cooler ride, and UV protection equivalent to SPF 285. Helps protect your seats and dash from harmful UV light and an additional layer of security from smash and grab theft.	1	775.00	775.00
This service includes window tinting of the sides and back glass with added tint for the full rear window.			
Percentages: 70% uniform			
Installations and Labor:Window Tint SUV (Ceramic) Solar Gard Vortex IR Ceramic tint film blocks up to 70% of solar heat for a cooler ride, and UV protection equivalent to SPF 285. Helps protect your seats and dash from harmful UV light and an additional layer of security from smash and grab theft.	1	395.00	395.00
This service includes window tinting of the sides and back glass with added tint for the full rear window.			
Percentages: 70%			

INITIALS: ____

TOYOTA MULTI-POINT INSPECTION

Customer Name: RYAN TU Phone: (C) (650) 799-6492 Vehicle Year/Model: 89 TOYOTA TRUCK LAND C Printed: 12/29/2022 13:08:30

VIN: JT3FJ62GXK1103951

Technician: CHRISTIAN T CRANK

Odometer: 117848 Tag: 1837 RO: 277629

Service Advisor: JOHN L DIAZ	Technician: CHRISTIAN T CRANK	RO: 277629	Tag: 1837
INSPECTION RESULT - OK	WILL REQUIRE FURTHER ATTENTION	School Strain Company	capacitativa.
Green Yellow Red	Servic	Front / Rear Bra	ko Linings
Driver Floormat Installation Ve	rified		RF
Engine Oil Level (on arrival)		☐ LF ☐ Green	Green 🔽
Windshield Washer Fluid		Green Yellow	Yellow
Coolant (degree of protection)		Red	Red 🔀
Power Steering Fluid (if equipped)	ped)	□ - \	<i>/</i> -
☑ ☐ Brake Fluid			22
Clutch Fluid (if equipped)		LR I	RR Green 🗸
▼ 🔲 📓 Transmission / Transaxle Fluid		☐ Yellow	Green Yellow
Differential Fluid (if equipped)		Red	Red 🕶
▼	lels)	The state of the s	(See Note)
Engine Air Filter		Inspection I	Not Taken
Cabin A/C Filter		7-12mm Disc, 3-	
✓ ☐ ☐ Horn Operation		4-6mm Disc, 2	
✓ ☐ ■ Brake System & Parking Brake	Operation	30 40 E 10 E 16	Matalia
Cooling System & Hoses		Check Tires / 1	Fread Denth
☑ ☐ ☑ Drive Belts		LF	RF
☑ ☐ Engine		Green	Green 🔽
Hybrid (if equipped)		Yellow	Yellow
▼ ☐ ■ Transmission & Transfer Case	(if equipped)	Red F	Red Red
Steering Linkage			
Front Suspension			97
Front Drive Axle & Differential	(if equipped)	LR Green	RR Green 🔽
Rear Suspension] Green	Yellow
Rear Drive Axle & Differential	(if equipped)	Red	Red 2
HVAC System]]	. —
▼ ☐ ■ Fuel Lines, Connections, & Fue	l Tank Gas Cap	7/32" or G	reater
Exhaust System		4/32" to 6	END I SERVICE ET A COLO I
✓ ☐ Windshield Washer and Wiper	Operation		
Exterior Lights & Lamps		Check Battery P	erformance
✓ ☐ ☑ Interior Lights & Lamps	<i>*</i>	Good	
✓ ☐ ■ Interior/Exterior Concern] Fair	
Recommended Maintenance] Bac	
Brake Inspection Comment: Rear: drums		Actual Cold Cranking	Amps
Brake Lining Measurements: LF: 7 mm RF: 7		Factory Cold Cranking	Amps -
Tire Tread Measurements: LF: 10/32" RF: 10,	'32" LR: 10/32" RR: 10/32"		,po

TOYOTA MULTI-POINT INSPECTION

fromer Name: RYAN TU

Vehicle Year/Model: 89 TOYOTA TRUCK LAND C Printed: 12/29/2022 13:08:30

hone: (C) (650) 799-6492

VIN: JT3FJ62GXK1103951

Odometer: 117848

Service Advisor: JOHN L DIAZ INSPECTION RESULT - OK Technician: CHRISTIAN T CRANK

Tag: 1837 RO: 277629

WILL REQUIRE FURTHER ATTENTION

Tire Tread Measurements: LF: 10/32" RF: 10/32" LR: 10/32" RR: 10/32"

Tire Pressure Measurements: LF: 35psi RF: 35psi LR: 35psi RR: 35psi

974645

TOYOTA SUNNYVALE

NET

90.00

FEB 2 0 2022

875.00

46.44

TOTAL

90.00

(N/C)

90.00

(N/C)

875.00

46.44

0.00

898 W. FL CAMINO REAL · SUNNYVALE, CA 94087

INVOICE

(408) 245-6640 www.tovotasunnyvale.com

LIST

В١

RYAN HUAIN TU Service Center Hours: 490 WEST M ST MONDAY - FRIDAY 7:00 AM - 7:00 PM BENICIA, CA 94510 PAGE 1 SATURDAY 7:00 AM - 6:00 PM SUNDAY 8:00 AM - 6:00 PM HOME: CONT: 650-799-6492 SERVICE ADVISOR: BUS: 3257 CELL: 650-799-6492 LOU MARINO COLOR YEAR MAKE/MODEL VIN LICENSE MILEAGE IN / OUT

TAG 103678/103678 89 JT3FJ62GXK110395 T9635 TOYOTA LANT RATE INV DATE DEL. DATE PROD. DATE WARR, EXP. PROMISED PAYMENT PO NO. 01JAN89 DD CASH 20FEB22 :00 18FEB22 B.O. OPENED DI.P · XXXXX READY OPTIONS: 18FEB22 20FEB22

LINE OPCODE TECH TYPE HOURS A CUSTOMER STATES OIL LEAK - ADVISE

FIO CUSTOMER STATES OIL LEAK - ADVISE

4028 C

511902 POWER WASH ENGINE

4028 ISP PARTS: 0.00 TOTAL LINE A: 0.00 LABOR: 90.00 OTHER: 103678 INSPECTED AND VERIFIED OIL LEAK PRESENT AROUND OIL PAN AND

OIL COOLER LINES. CLEAN OFF OIL RESIDUE AROUND PAN AND OIL LINES. APPLIED ENGINE OIL DYE INSIDE ENGINE CRANKCASE. LET VEHICLE RUN ON IDLE FOR 20 MINUTES. USED UV LIGHT AND GLASSES FOUND DYE AROUND FRONT AND REAR OIL PAN AND OIL COOLER HOSES. RECOMMEND REPLACING GASKETS,

O-RINGS, AND CLAMPS FOR REPAIR.

************ PERFORM MULTI POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY

SPECIFICATION, CUSTOMER ADVISED ON TOYOTA RECOMMENDATION TO NOT HAVE MULTIPLE OR LOOSE FLOOR MATS ON THE DRIVERS SIDE FLOOR AND TO HAVE THE RETAINERS HOLDING THE FLOOR MAT IN PLACE VI PERFORM MULTI POINT INSPECTION AND SET TIRE

PRESSURES TO FACTORY SPECIFICATION, CUSTOMER ADVISED ON TOYOTA RECOMMENDATION TO NOT HAVE MULTIPLE OR LOOSE FLOOR MATS ON THE DRIVERS SIDE FLOOR AND TO HAVE THE RETAINERS HOLDING

THE FLOOR MAT IN PLACE

4028 ISP 0.00 LABOR: PARTS: 103678 PERFORMED MULTI-POINT INSPECTION

0.00 OTHER: 0.00 TOTAL LINE B:

C** OIL PAN &/OR GASKET - R&R M041695 OIL PAN &/OR GASKET - R&R C 4028

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 SIZC IMAGING

12151-61011 GASKET, OIL PAN 46.44 00295-00103 FIPG OIL PAN 28.22 5.28

28.22 28.22 5.28 8 00279-1QT30-01 BT 10W30 MOTOR OIL W 42.24 2.73 73 2.73 90430-12028 GASKET DESCRIPTION TOTALS FINAL LABOR AMOUNT REVISED ORIGINAL

PARTS AMOUNT ESTIMATE: S ESTIMATE: \$ ADDITIONAL GAS, OIL, LUBE DATE TIME PHONE A ALITHORIZED AMOUNT SUBLET AMOUNT TOYOTA SUNNYVALE MISC. CHARGES SCION SUNNYVALE TOTAL CHARGES BAR # ARD010842 LESS ADJUSTMENTS EPA # CAD 980887418 I ACKNOWLEDGE RECEIPT OF VEHICLE AN HAVE RECEIVED A COPY OF THIS INVOICE SALES TAX I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE. PLEASE PAY

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

CUSTOMER COPY

RYAN HUAIN TU

490 WEST M ST

INVOICE

TOYOTA SUNNYVALE

898 W. EL CAMINO REAL · SUNNYVALE, CA 94087

BENICIA, CA 94510 www.toyotasunnyvale.com BUS: CONT:650-799-6492 PAGE 2 Service Center Hours: COLOR CELL:650-799-6492 MONDAY - FRIDAY 7:00 AM - 7:00 PM YEAR SERVICE ADVISOR: SATURDAY 7:00 AM - 6:00 PM MAKE/MODEL SUNDAY 8:00 AM - 6:00 PM 3257 VIN LOU MARINO 89 TOYOTA LANT DEL. DATE LICENSE PROD. DATE WARR. EXP. JT3FJ62GXK1103951 MILEAGE IN / OUT PROMISED TAG 01JAN89 DI PO NO. 103678/103678 R.O. OPENED RATE 12:00 18FEB22 T9635 PAYMENT READY INV. DATE OPTIONS: DLR:XXXXX 18FEB22 CASH 20FEB22 OPCODE TECH TYPE HOURS 20FEB22 1 90915-YZZD3 FILTER, PARTS: 125.04 OIL 103678 PERFORMED OIL PAN GASKET REPLACEMENT. CLEANED OIL PAN AND NET TOTAL MATTING AREA. TORQUE ALL OIL PAN BOLTS TO 6.1FT/LBS. REPLACED ENGINE 5.41 OIL AND OIL FILTER. USED 10W30 OIL. VERIFIED OIL PAN IS NOT LEAKING. 5.41 1000.04 D** ENGINE OIL COOLER HOSES- R&R M041643 ENGINE OIL COOLER HOSES - R&R 1 99556-30300 HOSE, WATER 2 96112-10250 CLAMP, HOSE 240.00 240.00 2 90430-18012 GASKET, TRANSMISSION 27.33 27.33 27.33 2 90301-21176 RING, O 1.16 1.16 2.32 4.06 00279-1QT30-01 BT 10W30 MOTOR OIL W 4.06 8.12 PARTS: 9.91 9.91 62.87 LABOR: 103678 PERFORMED ENGINE OIL COOLER HOSE REPLACEMENT, VERIFIED HOSES 19.82 5.28 5.28 302.87 ****** E** ENGINE COOLANT FLUID EXCHANGE SERVICE. CSFXL ENGINE COOLANT FLUID EXCHANGE SERVICE. 4028 CPM 1 BG5901 540,546 COOL SERV KIT 220.00 220.00 00272-1LLAC-01 ANTIFREEZE GALLON W 45.88 45.88 45.88 00272-1LLAC-01 ANTIFREEZE GALLON W 29.01 29.01 29.01 29.01 PARTS: 103.90 LABOR: 29.01 220.00 OTHER: 29.01 103678 PERFORMED COOLANT FLUID EXCHANGE SERVICE, VERIFIED COOLING TOTAL LINE E: 323.90 SYSTEM IS PROPERLY BLED FROM AIR. VERIFIED NO COOLANT LEAKS. EST: 331.78 20FEB22 11:30 SA: 3257 * Contact Method * CONTACT: RYAN PERSON !!!!!!! AUTHORIZED ESTIMATE WAS MODIFIED !!!!!!!! DESCRIPTION TOTALS FINΑ ORIGINAL LABOR AMOUNT REVISED ESTIMATE: \$ ESTIMATE: \$ PARTS AMOUNT AUTHORIZED ADDITIONAL AMOUNT DATE REVISED GAS, OIL, LUBE TIME PHONE # TOYOTA SUNNYVALE SUBLET AMOUNT SCION SUNNYVALE MISC. CHARGES TOTAL CHARGES BAR # ARD010842 LESS ADJUSTMENTS EPA # CAD 980887418 I ACKNOWLEDGE RECEIPT OF VEHICLE AND HAVE RECEIVED A COPY OF THIS INVOICE. SALES TAX I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE. PLEASE PAY THIS AMOUNT NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

CUSTOMER COPY

974645 RYAN HUAIN TU TOYOTA SUNNYVALE 490 WEST M ST *INVOICE* 898 W. EL CAMINO REAL SUNNYVALE, CA 94087 BENICIA, CA 94510 BUS: CONT:650-799-6492 www.toyotasunnyvale.com PAGE 3 MONDAY - FRIDAY 7:00 AM - 7:00 PM COLOR CELL:650-799-6492 YEAR SERVICE ADVISOR: MAKE/MODEL SATURDAY 7:00 AM - 6:00 PM SUNDAY 8:00 AM - 6:00 PM 3257 LOU MARINO 89 VIN TOYOTA LAND DEL. DATE PROD. DATE WARR, EXP. JT3FJ62GXK110395 MILEAGE IN / OUT 01JAN89 DD PROMISED TAG PO NO. R.O. OPENED 103678/103678 12:00 18FEB22 RATE PAYMENT READY T9635 OPTIONS: INV. DATE 18FEB22 DLR:XXXXX LINE OPCODE TECH CASH 20FEB22 20FEB22 EST: 0.00 TYPE HOURS !!!!!!! AUTHORIZED ESTIMATE WAS MODIFIED !!!!!!!! 18FEB22 08:27 SA: 3257 *************** LIST NET Contact Method *

THANK YOU FOR CHOOSING TOYOTA SUNNYVALE. YOU MAY BE SENT AN EMAIL FROM TOYOTA TO GRADE TODAY'S OVERALL SERVICE. IF FOR ANY REASON WE DID NOT PROVIDE YOU WITH TRULY EXCEPTIONAL SERVICE, PLEASE CONTACT YOUR ASSIGNED SERVICE PRIOR TO FILLING OUT THE SURVEY. CUSTOMER SATISFACTION IS OUR #1 GOAL

	ORIGINAL ESTIMATE: \$			FINAL REVISED ESTIMATE: \$			DESCRIPTION LABOR AMOUNT	TOTALS 1425.00
							PARTS AMOUNT	291.81
TOYOTA SUNNYVALE	DATE	TIME	PHONE #	AUTHORIZED	ADDITIONAL AMOUNT	REVISED	GAS, OIL, LUBE	0.00
SCION SUNNYVALE		, g. i., a.,					SUBLET AMOUNT	0.00
G COLOR SOMMY TALE							MISC. CHARGES	0.00
BAR # ARD010842							TOTAL CHARGES	1716.81
PA # CAD 980887418							LESS ADJUSTMENTS	0.00
10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.			HAVE RECEIVED A	RECEIPT OF VEHI COPY OF THIS I	CLE AND I NVOICE.	SALES TAX	26.63
							PLEASE PAY THIS AMOUNT	1743.44

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

right 2014 CDX Global, LLC SERVICE INVOICE TYPE 2 - SIZC - IMAGING



•		Ministra
		SERVICE INFORMATION Service to be performed:
	VEHICLE CONDITION	Description of service to be performed:
	VEHICLE CO.	Describes
- 15		
CUSTOMER AND VEHICLE INFORMATION 974645	10 OM	
AND VEHICLE INFORMATION		Initial Estimate: I hereby authorize the repair work and inspection described to be the repair work and inspection described to be the repair work and inspection described or articles the repair along with the necessary materials and agree that the repair along with the necessary manage to vehicle or articles
02/18/2022 Time In:		Initial Estimate: I hereby authorize the repair work and inspection described U.J. I hereby authorize the repair work and inspection described in the necessary materials and agree that performed along with the necessary materials and agree that performed along with the necessary materials and specific or article performed the necessary materials and specific performance that the necessary materials and specific performance that the necessary materials are specified in case of life, therefore your employees permission to
	S I CONTRACT	I hereby authors with the necessary
TU, KTAIL CA 94510 (dealer is not responsible to theth, or any cause beyonds to
Customer Name: 490 WEST M ST Address:		I hereby authorized the necessary interest performed along with le for loss or damage to vehicle or artures dealer is not responsible for loss or damage to vehicle or artures dealer is not responsible for lister, then, or any cause beyond their left in vehicle in case of fire, then, or any cause beyond their left in vehicle in case of fire, then, to any cause of the control. I hereby grant you and/or your employees permission to control. I hereby grant you and/or your employees permission to provide the vehicle as necessary for testing and inspection operated.
490 WEST W. 5		control. The vehicle as necessary to
V00IA22		purposes.
Today's Contact Phone #:		pulper
Small:		Customer declines access to spare tire
1989 Toyota LANT		Customer declines access to glove box
Year/Make/Model: 1989 Toyota LANT (103678 License#:		Customer con
	9635	Signature:
Micago	•	
J T 3 F J 6 2 G A N 1	Tag#:	00
VIN Hat /	lagir.	30 _B 30 _{Spare} ——
1/4 Time:Promise Time:	Factory Specs (P.S.I.)	F 30 R 30 Spare
	Tire pressure P.S.I. ch	necked / adjusted 30 30 RR
	√ , 30	. RF/LH
Head lights / tail lights / ta	LF	Spare not checked/adjusted
hazard warning lights / declaration Windshield wiper and washer operation	Opu	
× us debiold glass	Tread	depth: 10 32 10 32
Fuel tank cap gasket		depth: 10_/32_RF10_/32_LR10_/32_RR10_/32
and a combination meter		
Dome light / map light / dimmer combination meter	F Tire d	amage / abnormal wear:
Cabin air filter		_ pp Spare
Parking brake operation	LF	RF LR NI
Parking brake uperators Check installation of driver's floormat	Rims	/ wheels / lug nuts:
= =		
ox Channed HV battery cooling intake filter - inspect every 5k, clean every 20k (Not Applicable)	LF	
	Tires Rotated	Torque Spec:
Air filter Battery condition (cables / clamps / corrosion)		
Battery condition (causes a state)		
Battery state of health Cocling system (leaks) Hoses (cracks / damage / leaks) Drive betts (cracks / damage / wear)	Brake	lining:
Hoses (cracks / damage / leaks)	7	mm RF_7_mm LR_3>_mm RR_3>_mm
Drive belts (cracks / damage / wear)	LF	nm RFIIIII EI
		Front / Rear
(Oil level on arrival)		Disc Brakes
OK Filled Y	92	
✓ Windshield Washer ✓ Coolant Filled degree of protection)	Brakes	2-7 mm 6-4 mm 3-0 mm
Coolant (iiieddegree of protection)	ii	Rear Drum Brakes
Power steering (if equipped)		4-3 mm 2 mm 1-0 mm
Brake reservoir Clutch reservoir (if equipped)		4.5 mil
		e lines / hoses / parking brake cable
☐ Transmission / transaxle (☐ fluid not checked		
Differential (if equipped)	Discs	s / drums / calipers / wheel cylinders
Transfer case (4WD models)		
Propeller / driveshaft (damage / leaks / U-joints)	Comments	
Drive / CV shaft (damage / leaks / boots)		
Steering linkage (damage / leaks / worn components)		
Alle hub & bearing (damage / leaks / noise) Steering inface (damage / leaks / worn components) Suspension (damage / leaks / worn components) Fluid leaks (engine / transmission / differential) Exhaust system (damage / leaks / corrosion)		7 * 11 <u>-</u> 11
Fluid leaks (engine / transmission / differential)	Technician Team: Lou N	Marino John Biala
Exhaust system (damage / leaks / corrosion)	rechnician ream.	
Fuel lines & connections / fuel tank bands / fuel tank		NAME OF THE PARTY
vapor vent system hoses (damage / leaks / corrosion)	Checked and OK at this time	May require future attention requires immediate attention
		2000
Top — Customer C	Copy / Bottom — Dealer C	ору

Custom Cruisers
22690 Broadway #2
Sonoma, CA, 95476
Phone: 707-292-3509
Email: gary@mudrak.com
We can take you where you want

to go... and beyond



Inv	oice #	5607
	P.O.	7362
	Date	Jun 25, 2022
	Time	03:21 pm

	I	N V O I	C E		Page 1 of 1
	Year	1989	Mileage	Labor	\$200.00
Ryan Tu 3909 Park Rd Suite 2 Benicia, CA 94510 Cell: 650-799-6492	Make	TOYOTA	Tag	Parts	\$4,599.00
		LAND CRUISER	Vehicle #	Misc	\$0.00
	Model	4X4	venicle #	Subtotal	\$4,799.00
	Engine	4.0L MULTIPORT	FI	Tax	\$390.92
	VIN			Total	\$5,189.92

Labor

Description	Hours	Rate	Price	
Install Tent	1.00	\$200.00	\$200.00	

Parts

I UI U		MINNSON PARAMETERS STORES	NOW AND THE PROPERTY OF THE PARTY OF THE PAR	NAME AND ADDRESS ADDRESS ADDRESS AND ADDRESS A
Part No	Description .	Quantity	Unit Cost	Price
Columbus Large Grey		1.00	\$4,599.00	\$4,599.00

Misc.

A CONTRACTOR AND A STREET	Description	Lait lait	Quantity	Unit Cost	Price
No items					

Notes:

I consent to in-person, telephone or text message (via automated technology to the cell phone number you have on file)authorization for work performed on my vehicle. DATE SIGNED

I understand there is no warranty on customer supplied parts. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto, until such time as cash payment has been made in full. It is understood that M.C.c. Will in the held alreasynshib for loss or deposite or cars or articles left in cars in case of fire, their or any other cases beyond control of M.C.C. Upon signing this repair order it is accepted as a complete and comprehensive description of the repair work done on this vehicle. DATE

SIGNED

All special-order and made to-order items require foll payment at time of order and signing fee if cancelled. All Jucab and Autohome tent orders require a 50% deposit at time of order and are subject to a 25% restocking fee if cancelled or returned.

Cash Payment	\$5,189.92
Amount Due	\$0.00

SIGNED

DATE

ak Custom Cruisers

22690 Broadway #2 Sonoma, CA, 95476 Phone: 707-292-3509 Email: gary@mudrak.com We can take you where you want to go... and beyond



Invoice #	5618
P.O.	7364
Date	Jun 30, 2022
Time	08:30 pm

	I	N V O I	C E			Page 1 of 2
	Year	1989	Mileage	109,170	Labor	\$1,800.00
Ryan Tu 3909 Park Rd	Make	TOYOTA	Tag	8WGJ806	Parts	\$2,298.78
Suite 2 Benicia, CA 94510	Model	LAND CRUISER 4X4	Vehicle #	Grey	Misc	\$0.00
Cell: 650-799-6492	1				Subtotal	\$4,098.78
	Engine	4.0L MULTIPORT FI			Tax	\$195.40
	VIN	JT3FJ62GXK11039	951		17	4100.13
					Total	\$4,294.18

Labor

SEC

24501			
Description	Hours	Rate	Price
Install Suspension	1.00	\$1,500.00	\$1,500.00
Alignment	1.00	\$100.00	\$100.00
Repair Rear Light Emblem/Snake Blinder Clips/Fuel Filter	1.00	\$200.00	\$200.00

Parts

Part No	Description	Quantity	Unit Cost	Price
CS003F	OME LEAF SPRING	2.00	\$135.00	\$270.00
60009	OME NITROCHARGER SPORT SHOCK	2.00	\$132.00	\$264.00
60062	OME NITROCHARGER SPORT SHOCK	2.00	\$132.00	\$264.00
OMESB1	B/KIT 35mm	4.00	\$37.00	\$148.00
OMEU51	OME U BOLT WASHER & NUT	4.00	\$22.00	\$88.00
OMEU59B	OME U BOLT WASHER & NUT	4.00	\$24.00	\$96.00
OMEGS1	GREASABLE SHACKLE KIT REAR	1.00	\$152.00	\$152.00
OMEGP1	GREASABLE FIX END PIN KIT	2.00	\$87.00	\$174.00
OMEGS2	GREASABLE SHACKLE KIT	1.00	\$140.00	\$140.00

I consent to in-person, telephone or text message (via automated technology to the cell phone number you have on file) puthorization for work performed on my webtice. DATE
SIGNED

Inderstand there is no warranty on customer supplied parts. An express mechanical lien is advanted upon the above vehicle to secure the amount of repairs
thereto, until such time as cash payment has been made in full. it is understood that M.C.c. Will not be held responsible for loss or desponsible for loss or desponsible for loss or description of the repair work.

All special-order and made-order text message the payment at time of order and such as 50% restocking fee if cancelled, All other purchases are subject to a 25% restocking fee if cancelled or returned.

		Charge Payment	\$4,294.18
SIGNED	DATE	Amount Due	\$0.00

ustom Cruisers

2690 Broadway #2 Sonoma, CA, 95476 Phone: 707-292-3509 Email: gary@mudrak.com We can take you where you want to go... and beyond



Invoice #	5618
P.O.	7364
Date	Jun 30, 2022
Time	08:30 pm

	I	N V O I	C E			Page 2 of 2
	Year	1989	Mileage	109,170	Labor	\$1,800.00
Ryan Tu 3909 Park Rd Suite 2 Benicia, CA 94510 Cell: 650-799-6492	Make	TOYOTA	Tag	8WGJ806	Parts	\$2,298.78
	Model	LAND CRUISER	Vehicle #	Grev	Misc	\$0.00
		4X4			Subtotal	\$4,098.78
	Engine	4.0L MULTIPORT	FI		Tax	\$195.40
	VIN	JT3FJ62GXK1103	951		Total	\$4,294.18

Parts

Part No	Description	Quantity	Unit Cost	Price
CS005RA	OME LEAF SPRING	2.00	\$244.00	\$488.00
67772-20021	Caps For Snake Blinders	5.00	\$1.72	\$8.60
75867-20020	CLIP, ROCKER PANEL MOULDING	5.00	\$4.42	\$22.10
23300-69025	Fuel Filter	1.00	\$45.08	\$45.08
Rear Sway Extensions		1.00	\$50.00	\$50.00
germone kappanigas (o arriti Elizabate alt e electrosecont	Front Sway Extensions	1.00	\$89.00	\$89.00

Misc.

Description Description	Quantity	Unit Cost	Price
No items		Protectivity for the color of a state of a s	

Notes:

I consent to in-person, telephone or text message (via automated technology to the cell phone number you have on file)authorization for work performed on my vehicle. DATE

SIGNED

I understand there is no warranty on customer supplied parts. An express mechanics liem is acknowledged on the above vehicle to secure the amount of repairs
thereto, until such time as cash payment has been made in full. It is understood that M.C.C. will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other
cause beyond control of M.C.C. Upon signing this repair order it is accepted as a complete and comprehensive description of the repair work to this vehicle. DATE

SIGNED

All special-order and made-to-order items require full payment at time of order and subject to a 50% restocking fee if cancelled. All Autoba and Autobame
tent orders require a 50% deposit at time of order and are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases are subject to a 25% restocking fee if cancelled. All other purchases

		Charge Payment	\$4,294.18
SIGNED	DATE	Amount Due	\$0.00

Mudrak Custom Cruisers 22690 Broadway #2

Sonoma, CA, 95476 Phone: 707-292-3509 Email: gary@mudrak.com We can take you where you want to go... and beyond



	Invoice #	6028
	P.O.	7958
	Date	Mar 24, 2023
	Time	11.57 am

Page 2 of 3
60.00
16.62
30.00
06.62
79.96
86.58
3

Parts

Part No	Description	Quantity	Unit Cost	Price
90wt	Gear Oil	3.50	\$26.00	\$91.00
Cc1213	Aluminum Radiator	1.00	\$494.98	\$494.98
Coolant	Coolant	2.50	\$26.00	\$65.00
90916-02193-77	Fan Belt	1.00	\$27.99	\$27.99
90916-02141-77	BELT,V,FAN/ALTERNATOR	1.00	\$15.99	\$15.99
99332-11175-83	V-BELT COMPRESSOR	1.00	\$14.93	\$14.93
88440-35010	PULLEY ASSEMBLY, IDLE	1.00	\$40.88	\$40.88
16571-61110	HOSE, RADIATOR, INLET	1.00	\$39.29	\$39.29
ATF	Automatic Transmission /Power Steering Fluid	14.00	\$13.75	\$192.50
SS Battery Tray	SS Battery Tray 60-62	1.00	\$125.00	\$125.00
Trans Cooler	Company of the compan	1.00	\$99.00	\$99.00
7713	Rad Cap	1.00	\$18.99	\$18.99

I consent to in-person, telephone or text message (via automated technology to the cell phone number you have on file)authorization for work performed on my vehicle. DATE

SIGNED

I understand there is no warranty on customer supplied parts. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs
thereto, until such time as cash payment has been made in full. It is understood that M.C.c. will not be held responsible exceeded to the contract of M.C.c. Upon signing this repair of the contract of M.C.c. Upon signing this repair of the contract of M.C.c. Will not be held responsible exception of the repair work done on this vehicle. DATE.

SIGNED

To applie the second of the contract of M.C.c. Will not be held responsible exception of the repair work done on this vehicle. DATE.

SIGNED

To applie the second of the contract of M.C.c. Will not be held responsible exception of the repair work done on this vehicle. DATE.

SIGNED

To applie the second of the contract of the contract of the second of the repotlets are products and the second of the repotlets are products and the second of the repotlets are products and the second of the repotlets are second o

		Check Payment	\$11,286.58
SIGNED	DATE	Amount Due	\$0.00

ak Custom Cruisers

22690 Broadway #2 Sonoma, CA, 95476 Phone: 707-292-3509 Email: gary@mudrak.com We can take you where you want to go... and beyond



Invoice #	6028
P.O.	7958
Date	Mar 24, 2023
Time	11:57 am

	I	N V O I	C E			Page 3 of 3
	Year	1989	Mileage	112,850	Labor	\$5,160.00
Ryan Tu 3909 Park Rd	Make	TOYOTA	Tag	8WGJ806	Parts	\$5,616.62
Suite 2	Model	LAND CRUISER	Vehicle #	Grev	Misc	\$30.00
Benicia, CA 94510 Cell: 650-799-6492		4X4			Subtotal	\$10,806.62
001.000 750 0152	Engine	4.0L MULTIPORT FI			Tax	\$479.96
	VIN	JT3FJ62GXK1103951				\$170.00
1					Total	\$11,286.58

Misc.

Description	Quantity	Unit Cost	Price
HAZARDOUS WASTE FEE - EPA #CAL000396819	1.00	\$30.00	\$30.00

Notes: check # 169

I consent to in-person, telephone or text message (via automated technology to the cell phone number you have on file)authorization for work performed on my whicle. DATE
SIGNED

I understand there is no warranty on customer supplied parts. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs
thereto, until such time as cash payment has been made in full, or cash and there is no warranty on customer supplied parts. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs
thereto, until such time as cash payment has been made in full, or other lit. Is accepted as a complete such responsible for loss or damage to cars or articles left in cars in case of fire, that for any other
cases beyond control of M.C.C. Upon all apprecial order and made to complete such as a first of control and such as the control of t

		Check Payment	\$11,286.58
SIGNED	DATE	Amount Due	\$0.00

Toy Shop 4818 Geary Boulevard San Francisco, CA, 94118 Phone: 415-386-0122 Fax: 415-386-0185

INVOICE 53734

BAR #ARD239942

Ext

n/c

INVOICE

TU. RYAN 3909 PARK ROAD Benicia, CA 94510

Part Description / Number

763 Ter :

4818 (10.71.71)

Cellular 650-799-6492 -- Home 650-799-6492

Qtv

Sale

Date: 05/08/2021 1989 Toyota - Land Cruiser - 4L, In-Line6 (243CI) VIN(F)

Lic #: NOPLATES Odometer In: 91700

Unit #: 12/88 FJ62LG VIN #: JT3FJ62GX K1103951

Labor Description CUSTOMER REPORTS: LOSS OF POWER WHEN

DRIVING AT FREEWAY SPEEDS, INSPECT AND REPORT.

JOB #1

270.00 CHECK ENGINE COMPUTER FOR TROUBLE CODES, NO TROUBLE CODES. CHECK ENGINE TUNE UP CONDITION AND SPECIFICATIONS, TUNE SPECIFICATION OUT OF ADJUSTMENT. RESET TIMING AND TUNE UP SPECIFICATION, CHECK EFI SYSTEM AND SENSORS, CHECK IGNITION SYSTEM AND COIL VOLTAGE OUTPUT, OK. CHECK AND REPLENISH FLUID LEVELS, ROAD TEST ENGINE PERFORMANCE *RECOMMEND INSPECT AND TEST COLD START INJECTION SYSTEM, LONG CRANKING TIME WHEN STARTING AT TIMES.

INSPECT SUSPENSION AND STEERING SYSTEM, STEERING UNSTABLE WHEN DRIVING OVER ROUGH ROADS, STEERING WHEEL OFF CENTER, RECOMMEND REPLACING STEERING DAMPER WITH STRONGER UNIT (HEAVY DUTY TYPE) AND HAVE FRONT END WHEEL ALIGNMENT.

SAN FRANCIS (1 4 94118 1-18-2021 16:1 GED: GC With Sales 27.4 Hillard VISA CR II 4/1000000003 11 1 E31.90 6001 A A DECE L'iova Code: 00 : Method: Chip 1 1: 1: , LE AMOUNT \$271 CUSTOMERION

Vehicle Received: 05/08/2021

Org. Estimate 270.00 Revisions 0.00 Current Estimate 270.00

Labor: 270.00 arts 0 00

SubTotal: 270.00 Tay. 0.00 Total: 270.00 Bal Due: \$270.00

Customer Number: 13266

Thereby authorize the above repair work to be done along with the necessary material and hereby grant Toy Shop and/or your employees permission to operate the vehicle described The testing and/or inspection. Service work performed is warranted for testing and/or inspection. Service work performed is warranted for it testing and/or inspection. Service work performed is warranted for It zerother or 12 down lies with every cocus first, we not occur abuse or misuse, work under this warranty must be done in our shop, unless authorized by TOY SHOP. Repair, replacement or refund will be at our discretion. We do not warranty or guarantee parts supplied by vehicles owner. This warranty is non-transferable. Toy Shop is not responsible for loss or damage to cars or articles left in cars

Signature

Email Address: TOYSHOPBILLING@GMAIL.COM

Page 1 of 1

Copyright (c) 2021 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

Toy Shop 4818 Geary Boulevard San Francisco, CA. 94118

Phone: 415-386-0122 Fax: 415-386-0185

INVOICE 54834

BAR #ARD239942 EPA #CAL000334247

Date: 09/18/2021

INVOICE

TU. RYAN 3909 PARK ROAD

Benicia, CA 94510 Cellular 650-700-6492

Home 650-799-6492

1989 Toyota - Land Cruiser - 4L, In-Line6 (243CI) VIN(F) Odometer In: 98633 Lic # · NOPLATES

Unit #: 12/88 FJ62LG

VIN # : .IT3F.I62GX K1103951

Cellular 650-799-6492 Home	9-691-000	492		VIII # . 5151 802 CX RETIGORS 1	
Part Description / Number	Qty	Sale	Ext	Labor Description	E
OIL, MOTOR 10W/40 KENDALL	7.00	4.25	29.75	CUSTOMER REPORTS: CHANGE ENGINE OIL. REPLACE STEERING DAMPER. ENGINE HARD TO START, CRANKS ONLY, INSPECT AND REPORT.	n/c
FILTER, OIL 90915-YZZD3	1.00	5.41	5.41	OIL AND FILTER CHANGE. CHANGE ENGINE OIL, INSTALL GENUINE TOYOTA OIL	21.6 FILTER.
GASKET, DRAIN PLUG 90430-12028	1.00	1.67	1.67	REPLACE PLUG GASKET. CHECK AND REPLENISH FL LEVELS. SET TIRE PRESSURES. CHECK LIGHTS.	LUID
				JOB #2: REMOVE AND REPLACE STEERING DAMPER. CHECK STEERING OPERATION, ROAD TEST, *CUSTOMER SUI	75.0 PPLIED

n/c JOB #3: INSPECT AND TEST STARTING SYSTEM, COLD START INJECTION SYSTEM INOPERATIVE, TEST FUEL INJECTOR AND CIRCUITS, FUEL INJECTOR INOPERATIVE, CLEAN AND UNCLOG INJECTOR, RECHECK INJECTOR OPERATION, OKAY. TEST COLD START THERMAL TIME SWITCH AND CIRCUITS, OKAY, ENGINE COMPARTMENT COOLING FAN INOPERATIVE CHECK FUSES AND RELAY, OKAY. RECOMMEND INSPECT AND TEST FAN MOTOR AND CIRCUITS.

OWN PART, NO WARRANTY ON PARTS OR LABOR

Current Estimate 136.58 0.00 Org. Estimate 136.58 Revisions

This warranty is non-transferable. Toy Shop is not responsible for loss or damage to cars or articles left in cars

96.62 Labor: Parts: 36.83 133.45 SubTotal: 3.13 Tax: 136 58

[Payments -]

Vehicle Received: 09/18/2021

Total: \$136.58 Bal Due: Customer Number: 13266

Thereby authorize the above repair work to be done along with the necessary material and hereby grant Toy Shop and/or your employees permission to operate the vehicle described for testing and/or inspection. Service work performed iss warranted for 12 months or 12,000 miles, whichever occurs first, we will not cover abuse or misuse, work under this warranty must be done in our shop, unless authorized by TOY SHOP. Repair, replacement or refund will be at our discretion. We do not warranty or guarantee parts supplied by vehicles owner.

Signature Email Address: TOYSHOPBILLING@GMAIL.COM

Page 1 of 1

Copyright (c) 2021 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

Toy Shop 4818 Geary Boulevard San Francisco, CA. 94

San Francisco, CA. 94118 Phone: 415-386-0122 Fax: 415-386-0185 INVOICE 55650

55650 BAR #ARD239942 EPA #CAL000334247

INVOICE TU, RYAN

Date: 12/17/2021 1989 Toyota - Land Cruiser - 4L, In-Line6 (243CI) VIN(F)

3909 PARK ROAD Lic ≠
Benicia, CA 94510 Unit

Lic # : 8WGJ806 Odometer In : 0 Unit # : 12/88 FJ62LG

650-799-6	6492		VIN # : JT3FJ62GX K1103951	101461
Qty	Sale	Ext		Ext
1.00	82.20		CUSTOMER REPORTS: CHECK BRAKES.	n/c
1.00	116.39	116.39	FRONT: 2mm(DISC) REAR: 3mm(DRUM) INSPECT	450.00 BRAKE
2.00	71.56	143.12	PADS WORN NEAR MINIMUM, RIGHT REAR WHE WORN AND LEAKING BRAKE FLUID, REMOVE AN	EL CYLINDER ND REPLACE
1.00	9.25	9.25		EEL PLATES, FLUSH
	1.00 1.00 2.00	Qty Sale 1.00 82.20 1.00 116.39 2.00 71.56	Qty Sale Ext 1.00 82.20 82.20 1.00 116.39 116.39 2.00 71.56 143.12	City Sale Ext Labor Description

Org. Estimate 830.79 Revisions 0.00 Current Estimate 830.79

Labor: 450.00 Parts: 350.96 SubTotal: 800.96 Tax: 29.83 Total: 830.79 Bal Due: \$830.79

Customer Number: 13266

[Payments -]

Vehicle Received: 12/17/2021

I hereby authorize the above repair work to be done along with the necessary material and hereby grant Toy Shop and/or your employees permission to operate the vehicle described for testing and/or inspection. Service work performed iss warranted for 12 months or 12,000 miles, whichever occurs first, we will not cover abuse or misuse, work under this warranty must be done in our shop, unless authorized by TOS SHOP. Repair, replacement or Ferlund will be at our discretion. We do not warranty or guarantee parts supplied by vehicles owner. This warranty is non-transferable. Toy Shop is not responsible for loss or damage to cars or articles left in cars

Signature

Date

Email Address: TOYSHOPBILLING@GMAIL.COM

Page 1 of 1

Copyright (c) 2021 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

Specter Off-Road, Inc. Top Quality Land Cruiser Parts

21600 Nordhoff St., Chatsworth, CA 91311 USA (818) 882-1238 FAX: (818) 882-7144 CUSTOMER SERVICE: (818) 882-2365

WWW.SOR.COM, Email: SOR@SOR.COM

Cust # : 168272 TU, RYAN 3909 PARK ROAD, SUITE H

BENICIA CA 94510 (650) 799-6492



Invoice Number 1200103 03/14/22 24 1460215

Ship To: TU, RYAN 3909 PARK ROAD, SUITE H

> BENICIA CA 94510 (650) 799-6492

ORDER DATE 03/14/22		SHIP VIA UPS				Page 1 of	age 1 of 1 1989 ?		
LINE	QTY ORD	QTY SHIP	QTY B/O	ITEM NUMBER	DESCRIPTION	CORE/BOX	PRICE	EXTENSION	
1	1	1	0		INTERNET REQ	0.00	0.00	0.00	
2	100	- E		ORDER # d817451 Cust Request UP	i i i een	eders A. L. Sta			
4	1	. 1	0	1ST TIME ORDER	1ST TIME ORD	ER 0.00	0.00	0.00	
5	1	1	0	106-66C	RR 60/62BUMP	ER 16.25			
6	2	2	0	*139-09C-A	AFT*STAY ASS		55.00	110.00	
7	1	1	0	CONTRACTOR STATE OF THE STATE O		0.00	0.00	0.00	
8	- 1070	301.5		WILL CONTACT CU	ST RE: 1ST TI	ME QUST POLI	CY/CH	Janes Baller	
9				09:35:25 14 Ma	r 2022 Monda	y - Crystal		continuent committee and committee and	
10		13.780.000		CALLED CUST. SP	OKE WITH RYAN	, EPLAINED 1	ST TIME	300	
11				CUST POLICY	SAID OK TO SH	IP TO BILLIN	ng address	· ·	
12				OK TO PROCESS	.CH			4.1.4.1	
	1.00			Paragraph and the second		all Somethic	Action (
		1 15 15				100 200 100 100		S24	
			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		27				

NO RETURNS after 30 days - No exceptions NO RETURNS on electrical parts. NO RETURNS on books and manuals.

NO RETURNS on used or installed parts.

NO RETURNS on special order merchandise.

ALL RETURNS SUBJECT TO 20% RESTOCK FEE

Sub Total	663.89
Freight & Handling	54.45
Tax	63.07
Invoice Total	781.41
Amount Paid	781.41
Balance to collect	0.00



\$162.00

#194-80K-A Fit's 8/80-1/90 FJ60/FJ62 Comes with reservoir cap & grommet.



\$159.00

#130-03A-KIT Fits 8/80-1/90 60 & 62 Series - Kit for all 4 doors comes with clips #130-65



\$265.00

#113-80-A-PAIR Fits 1968-1979 FJ55 -Does not have groove for chrome strip. Sold in a pair - Reproduction



\$249.00

#128-30A-KIT Fits 1968-5/77 FJ55 - Kit includes front doors and rear passenger door weatherstrips.

Prices subject to change without notice, some items priced while quantities last.

Toy Shop4818 Geary Boulevard
San Francisco, CA. 94118
Phone: 415-386-0122 Fax: 415-386-0185

56714

BAR #ARD239942 EPA #CAL000334247 Date: 04/15/2022

Ext

n/c

90.00

J. RYAN

3909 PARK ROAD Benicia, CA 94510

Part Description / Number

ÓICE

Cellular 650-799-6492 -- Home 650-799-6492

Qtv

Sale

1989 Toyota - Land Cruiser - 4L, In-Line6 (243CI) VIN(F)

Lic #: 8WGJ806 Odometer In: 106122

Unit #: 12/88 FJ62LG

VIN # : JT3FJ62GX K1103951

Labor Description

CUSTOMER REPORTS: REPLACE REAR BUMPER.

REPLACE HATCH STRUTS.

JOB #1:

REMOVE AND REPLACE REAR BUMPER. CHECK BUMPER BRACKETS AND MOUNTS. "CUSTOMER SUPPLIED OWN PART, NO WARRANTY ON PARTS OR LABOR. "REPLACEMENT BUMPER END CAPS ARE INCORRECT FOR YEAR MODEL.

JOB #2:

45.0
REMOVE AND REPLACE HATCH LIFT SUPPORT STRUTS AND
MOUNTS. CHECK OPERATION, OKAY. *CUSTOMER SUPPLIED
OWN PARTS, NO WARRANTY ON PARTS OR LABOR

Org. Estimate 135.00 Revisions 0.00 Current Estimate 135.00

Rains

[Payments -]

Vehicle Received: 04/15/2022

Customer Number: 13266

Thereby authorise the above repair work to be done along with the necessary material and hereby grant Toy Shop and/or your employees permission to operate the vehicle described for testing and/or inspection. Service work performed iss warranted for 12 months or 12,000 miles, whichever occurs first, we will not cover abuse or misuse, work under this warranty must be done in our shop, unless authorized by TOY SHOP. Repair, replacement or refund will be at our discretion. We do not warranty or guarantee parts supplied by vehicles owner. This warranty is non-transferable. Toy Shop is not responsible for loss or damage to cars or articles left in cars

Signature

Email Address: TOYSHOPBILLING@GMAIL.COM

Page 1 of 1

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

Toy Shop 4818 Geary Boulevard

San Francisco, CA. 94118 Phone: 415-386-0122 Fax: 415-386-0185 INVOICE 58008

BAR #ARD239942 EPA #CAL000334247 Date: 10/07/2022

INVOICE

TU, RYAN 3909 PARK ROAD

Benicia, CA 94510

Cellular 650-799-6492 -- Home 650-799-6492

1989 Toyota - Land Cruiser - 4L, In-Line6 (243CI) VIN(F)

Lic #: 8WGJ806 Odometer In: 112388

Unit #: 12/88 FJ62LG

Cellular 650-799-6492 Home	650-799-	6492		VIN # : JT3FJ62GX K1103951	
Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
PUMP ASSEMBLY, FUEL 23220-16430	1.00	474.43	474.43	CUSTOMER REPORTS: REPLACE FUEL PUMP. CHECK AIR CONDITION, NOT COLD.	n/c
FILTER, SUCTION SCREEN 23217-61010	1.00	29.97	29.97	JOB #1: DRAIN FUEL SYSTEM AND REMOVE GAS TANK, REMOV	375.00 E AND
CLA:JP, HOSE SPRING SMALL 96135-51300	2.00	3.24	6.48	REPLACE FUEL PUMP AND FILTER SCREEN, RE-INSTAL	L GAS
				JOB #2:	75.00

CHECK AIR CONDITIONING SYSTEM, FREON LEVEL LOW CAUSING INSUFFICIENT COOLING, INSPECT AND TEST FOR LEAKS, NO LEAKS DETECTED AT THIS TIME. RECHARGE SYSTEM, CHECK OPERATING PRESSURES AND VENT TEMPERATURES, OKAY. ADD FREON FOR FUTURE LEAK DETECTION.

Org. Estimate	1,004.94	Revisions	0.00	Current Estimate	1,004.94		Labor:	450.00
						\leftarrow		450.00
						_	Parts:	510.88
						4		
						\sim		
						_	1	
						0	SubTotal:	960.88
						40		
							Tax:	44.06
							Total	1 004 04

[Payments -] Vehicle Received: 10/07/2022

\$1,004.94 Customer Number: 13266

I hereby authorize the above repair work to be done along with the necessary material and hereby grant Toy Shop and/or your employees permission to operate the vehicle described was under the developed which to be during a finish with the leveloped part of the store and provided part of the store and the

Signature Date

Email Address: TOYSHOPBILLING@GMAIL.COM

Page 1 of 1

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

Bal Due:

6/27/22 4:14 PM Store 202 Invoice # 2608399 BAR Registration # ARD293231

Lube Technician 8017

BAR Registration # ARD29 Hood Technician 11302 OIL CHANGERS 2762 El Camino Real Redwood City, CA 94061 (650) 366-5394

Manager Joe Magana Asst. Manager Rolando Medina

1-800-640-2405 Monday-Friday 8am-7pm			wwv Sa	info@oilchangers.com Sunday 9am-5pm			
Customer	Year	Make	Model	Engine	VIN	License	Mileage
Tu, Ryan	1989	Toyota	Land Cruiser	[F] 6 Cyl 4.0 L(-)	JT3FJ62GXK1103951	8WGJ806	109046

CI	HECKLIST
Item	Status
Coolant Reservoir	Full
Air Filter	Unable to Check
Washer Fluid	Filled
Brake Fluid	Checked
Battery	Maintenance Free
Wash Windshield	Completed
Lights	Checked
Under Hood	Inspected
Under Vehicle	Inspected
Tire Pressures	Checked/F 65 R 65
Lubrication Points	SealedFittings
Torque Drain Plugs	Completed
Free Top Off	Before 3 Mos & 3000 Mi

SERVICES		
Description	Qty	Price
FULL SERVICE SYNTHETIC OIL CHANGE	1.000	89.99
KENDALL 5W30S GT-1 MAX, GF-6 (Dexos1 GEN2) /SP SN+ (BULK)	5.000	
KENDALL 5W30S GT-1 MAX, GF-6 (Dexos1 GEN2) /SP SN+ (BULK)	3.200	28.77
TL30001 OIL FILTER	1.000	
OIL SURCHARGE	1.000	1.50

Date	Mileage	Services
2022-06-27	109046	LOF
Z0ZZ-00-Z7	***************************************	
	COMM	IENTS.





Subtotal	\$120.26
Tax (9.875%)	\$8.07
Total	128.33
Amount Due Today	\$128.33
Visa	(\$128.33)
Change	\$0.00

Credit 5737 Amt: 128,33 Mthd: Visa Auth Code:027674 Trans ID: 4045322293 Ad: A0000000031010 AppLabet VISA CREDIT Cryptogram: ARQC Entry: EMV Response: 00APPROVED

Signature I confirm that I understand the claim procedures and approve all prices.

		1	A	A A	PM	1	1	1	Щ	4		69					100						1	×		1					3
	-28-21	IEVED	The same				Street, or other street	Ldy NO.	LAROR CHARGE	· 98	<	1	N. C.	U										oc					et .		500
	DATE 6-23	TIME RECIEVED		Promised	Section 1999	Written By	Cust. Order No.	Phone when ready	LABOR	TION		N. S.					*					TOTAL	PARTS	CERT	HAZARD	SUB TOTAL	SALES TAX	LABOR	Star	ETF	TOTAL (A).
	DAT		26	Pro	ereby grant d on streets,	ster to will Writh	Cus			SMOG INSPECTION			1000				-									S	8		reassembled	not to	
	70		2617-14-05		ssary material and he licle herein described	n express mechanic's ount of repairs there ichie in case of fire, th	1		(SIGNATURE OR INITIALS)	SMOG							M.					ND LABOR	AUTHORIZED BY:	TIME	:No	AUTHORIZED		TIME	ny vehicle will	ve it i choose	
SMOS CHECK SMOS CHECK INSPECTION A REPAIR STATION	ryantop yallop.com	Tel. Bus.	Tel. Home 65	0.0.0	he along with the nece ite the car, truck or vel	gand/or inspection. A file to secure the arr is of articles left in vet			(SIGN)								200					TEARDOWN ESTIMATE - PARTS AND LABOR	AUTHC BY:	DATE	REASON:	AUTH	BY:	DATE	TEARDOWN ESTIMATE: I understand that my vehicle will reassembled	nened.	
4062 intment	Jutur	Tel.	Tel.)	ir work below be don s permission to opera	the purpose of testing those car, truck of well to damage to vehicle	you control	ICE AND ORAL REASE IN THE	PRICE.		1000			N. San		1	Shoe Till					ESTIMATE							STIMATE: I un	authorize the services recommened.	100
ity, CA 9 3y Appoi		Apt. No.		AVA	by authorize the repa	vays or elsewhere for a y acknowledged on a e responsible for loss,	orized By	CNOWLEDGE NOTICE SOVAL OF AN INCR	ORIGINAL ESTIMATED PRICE.						ł	24	The state of the s					TEARDOWN	ORIGINAL	PHONE	REVISED ESTIMATES	ADDITIONAL	COSTS	IN PERSON PHONE #	EARDOWN ES	uthorize the se	
Test Center T75 El Camino Real - Redwood City, CA 94062 Mon - Sat: 9:00am - 6:00pm Sun: By Appointment Tel: (650) 839-0888	Sellenge.	Ap	Zip	License No.	Iherel	highw hereb not by	or any Auth				-	in the second			- 1	n to	7	(9)	Mr.		*		T	Six		,	-1		IF	ai w	
Test Center El Camino Real • Redwood City, CA 9406 Sat: 9:00am • 6:00pm Sun: By Appoint Tel: (650) 839-0888	The state of			1			_	ar:	AIR ORDE							1							Die	4/	RVICE			Section of the sectio			1
Test mino Re 9:00am	Service Servic			Year-Make-Model 1989 Lanteing			The state of the s	APPROVED BY	REF													S	Coul	11/1	RECOMMENDED SERVICE:				4		ALL PARTS INSTALL
75 El Ca n - Sat:	1 /U			1861	.:	II.:																BILLING	redit	be of asura	MMEN					4	RTS IN
Mo ARD289181	Puba	, ss		lake-Mode	ESTIMATE AMT .:	ADD'L AUTH. AMT.:	REVISED ESTIMATE:		0													100	1	he o	RECO						L PAF
ARD ARD	Name	Address	City	Year-N	ESTIM	ADD'L	REVISI	TIME	ORDER NO													[ER	1.	2.	3.	4	5.	H AL
SALE	-										1	-												ACILITY TO HICH THE	A CUSTOM			-	-		
										1	and a											,		HORIZED F	CESSARY.	CETT					
CKIPTIO										- American		-											ARTS	OR ADJUS	S ARE NE	TOTAL NEGO	REPAIRS	1			RFPAIRS
PAKI NO. OK DESCRIPTION											Abore	The last							1		Sandal Land	side	TOTAL PARTS	HOOSE AND	INDICATE	WINST LC.	SUBLET REPAIRS			1	TOTAL SPECIAL REPAIRS
TAX.										14		4.		1	1		1			1	1	Additional Materials from reverse side	ř	BY LAW YOU MAY CHOOSE ANOTHER AUTHORIZED FACILITY TO PEREORM ANY NEEDED REPAIR OR ADJUSTMENTS WHICH THE	SMOG CHECK TEST INDICATES ARE NECESSARY. A CUSTOMER	OR FAIL.	*	1	1		TOT
			1	20	1		100	1	1				1								3	4		3Y LAW Y	SMOG CI	OF PASS OR FAIL.		1	-		

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 06/28/2021 @ 09:54 AM LAND CRUISER Model 1T3FJ62GXK1103951 TOYOTA Make: VIN: All Other Locations or Unknown Automatic Model-Year: State: Transmission: NONE License: Truck Cylinders: Tyne: Engine Size: 4 00 1 21537 4750 Test Weight: VLT Record #: 5620 GVWR-Initial Registration California Certification: Inspection Reason: 93603 Odometer Exhaust: Single

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Comprehensive Visual Inspection: PASS Smog Check Certificate Number: IL684501C

DMV ID Number: 5176L5981711

Gasoline

Fuel Type:

Your Smog Check certificate will be electronically transmitted to DMV

Please keep this copy for your records

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankease and cold start emission which are not measured during the ASM tests.) Emission Control Systems Visual Inspection/Functional Check Results Fuel Evaporative Controls

RESULT Fuel Tank Cap Visual Thermostatic Air Cleaner ECS RESULT PASS-N/A-Pump Air Injection Carburetor PCV PASS-N/A-PASS-Wiring of Other Catalytic Converter Ignition Spark Controls PASS-PASS-O2 Sensors and Connectors PASS-Sensors or Switches Visual EGR PASS. Ignition Timing: 7 BTDC DASS. Other Emission Related Fuel Injection PASS-PASS-Vacuum Line Connections DASS. Liquid Fuel Leaks Functional EGR PASS-PASS-N/A-Fuel Cap Functional Fill Pipe Restrictor PASS-N/A-MIL PASS-Fuel Evap Test

ASM Emission Test Results

PASS-	Fuel Evap test	ASM Emission Test Results	
Test RPM 15 mph 1547 25 mph 1566	CO2 (%) (%) MEAS MEAS 14.60 0.13 14.60 0.05	MAX AVE MEAS MAX AVE MEAS MAX AVE MEAS MAX AVE MEAS MAX OF 25 0.63 0.06 0.02 986 226 104 PA	ASS ASS Ount Measured

MAX = Maximum Allowable Emissions

Smog Check Inspection Station Information

AIR CARE 75 EL CAMINO REAL REDWOOD CITY 94062

Station Number: RC289181

Vi

Date

Technician Name/Number: NGUYEN, HUNG/EO638149

Repair Tech. Name/Number: N/A

Software Version/EIS Number: 1908/WP392571

650-839-0888 1 certify, under penalty of perjury under the laws of the State of California, that I inspected the vehicle described above, that I performed the inspection in

accordance with all bureau requirements, and that the information listed on the vehicle inspection report is true and correct.

Certificates are valid for 90 days from date of issuance

LU INVNES 5.1221ki

Signature

RON RAMIES INC.

115 PORTOLA ROAD Portola Valley, CA. 94028

Phone: 650-851-6789 Fax: 650-851-4041 ***WE NEVER GIVE UP***

INVOICE 72737

72737 Org. Est. # 123539 BAR # ARD158261 EPA CAL000472023

INVOICE

Printed Date: 11/03/2022

Work Completed: 11/03/2022

TU, RYAN 277 VISTA VERDE 1989 Toyota - Land Cruiser - 4L, In-Line6 (243CI) VIN(F) Lic #: 8WGJ806 Odometer In:

Odometer In: 112428 Odometer Out: 112428

Portola Valley, CA 94028

VIN # : IT3E.62GX K1103951

Cell 650-799-6492		VIN #: JT3FJ62GX K1103951		
art Description / Number Qty Sale I	Ext	Labor Description	Hours	Ex
		SMOG TEST 1976-1995 WITH EVAP TEST	1.00	140.0
	. 1.1	SMOG CERTIFICATE		8.2
		TIRE PRESSURE CHECK		nc
		TIRE PRESSURE		
		LF_32 RF 32		
		RR_32		
		LR_32		
		appoint of the contract of the contract of		
		A Secretaria de la companya della companya della companya de la companya della co		
		at And Commission Section		
		lasi datai k		
		a telephone in a special transition of		
and the second of the second o	100	The Color of the C		
Org. Estimate 148.25 Revisions 0.00 Current Estimate	14	La	bor:	148.25
		Pa	rts:	0.00
		Su	bTotal:	148.25
		Ta		0.00
		То	tal:	148.25

STORAGE FEE \$220@PER DAY

ve	hicle	Received:	11/3/2022

[Payments -]

Customer Number: 7997

\$148.25

Bal Due:

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty is ninety days or 4,000 miles whichever occur first. Warranty work must be performed by Ron Ramies Auto, Inc. & cannot exceed the original cost of repair.

Signature

Date

Visit us on the web: www.RONRAMIESINC.COM

Email Address: RON@RONRAMIESING.COM

Service Advisor : GARNICA, ELIANA, Tech : FAURE, MAT MF

Page 1 of 1

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Smog Check Vehicle Inspection Report (VIR)



High Emitter Profile

Certification:

Exhaust:

Date/Time: 11/03/2022@08:42:07

Vehicle Information

LAND CRUISER Model:

VLT Record #:

Inspection Reason:

odel Year: 1989 Make: TOYOTA JT3FJ62GXK1103951 VIN: 8WGJ806 State: CA License Automatic Transmission: Engine Size: 4.00 L Type: Truck Cylinders: 4750 GVWR: 5620 Test Weight: 21537

Federal

Single

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping

Pass

your vehicle well maintained.

Odometer:

Fuel Type

Pass

Smog Check Certificate Number: SY839101

112,428

Gasoline

DMV ID Number: 5475Y694S361

Your Smog Check certificate has been electronically transmitted to DMV. Your certificate is valid for 90 days from date of issuance

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

ECS Result **ECS** Result **ECS** Result Fuel Evaporative Controls Pass Thermostatic Air Cleaner PCV Not applicable Pass OBD System Checks Pass Air Injection Catalytic Converter Pass Pass Carb. / Fuel Injection Vacuum Lines to Sensors / Switches Pass Pass EGR Visual Pass Other Emission Related Components Pass EGR Functional Pass Ignition Timing: PB07 Not applicable Oxygen Sensor Pass Wiring to Sensors Fuel Cap Functional Pass Pass Liquid Fuel Leaks Fillpipe Restrictor Pass Fuel Cap Visual Not applicable Pass

ASM Emission Test Results

Fuel Evaporative Controls Functional

		%CO2	%O2	HC (PP	M)		CO (%)	- 11		NO (PP	M)		
Test	RPM	MEAS	MEAS	MAX	ÁVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1562	15.4	0.0	80	26	59	0.63	0.06	0.10	986	226	31	Pass
25 mph	1592	15.4	0.0	66	22	23	0.82	0.08	0.05	846	200	24	Pass
		lowable Er						or Passi	ing Vehicles		MEAS =	Amount M	easured

MAX = Maximum Allowable Emissions

RON RAMIES AUTOMOTIVE INC

115 PORTOLA ROAD

650-851-6789 Station Number: RC158261

Spark Controls

Smog Check Inspection Station Information

Technician Name/Number: Repair Tech Name/Number: Software Version/EIS Number:

1905 / EP525676

FAURE, MATHEW/EO152148

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this yehicle inspection report is true and accurate

Ma∤ 2022 ician's Signature Date