



Vehicle History Report™

2023 MERCEDES-BENZ SPRINTER 2500

VIN: W1X4NBVY4PT122088
CARGO VAN
2.0L I4
DIESEL
ALL WHEEL DRIVE



No accidents or damage reported to CARFAX



Regular oil changes



At least 1 open recall



CARFAX 1-Owner vehicle



Personal vehicle



2,467 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/7/25 at 4:29:03 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.



No Issues
Reported

Structural Damage

No structural damage reported to CARFAX.



No Issues
Reported

Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues
Reported

Odometer Check

No indication of an odometer rollback.



No Issues
Indicated

Accident / Damage

No accidents or damage reported to CARFAX.



No Issues
Reported

Manufacturer Recall

At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.

Recall Reported

Basic Warranty

Original warranty estimated to have 31 months or 33,533 miles remaining. Confirm with dealer or vehicle manufacturer.






Warranty
Active




Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	 Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	 Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2024
Type of owner	Personal
Estimated length of ownership	10 months
Owned in the following states/provinces	California
Estimated miles driven per year	---
Last reported odometer reading	2,467

CARFAX

Detailed History

Owner 1

Purchased: 2024




Personal Vehicle

Date	Mileage	Source	Comments
04/21/2023	2	<div>Loeber Motors, Inc.</div> <div>Lincolnwood, IL</div> <div>847-675-1000</div> <div><div>★</div><div>4.5 / 5.0</div></div> <div>172 Verified Reviews</div> <div><div>♥</div><div>154 Customer Favorites</div></div>	<div><div><div></div><div></div></div><div>Vehicle serviced</div><div>- Pre-delivery inspection completed</div></div>
04/18/2024		Mercedes-Benz USA LLC	<div><div>Manufacturer Safety recall issued</div><div>- NHTSA #24V166</div><div>- Recall #2024030019</div><div>- Status: Remedy Available</div></div> <div><div>Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall</div></div>

Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Sprinter vehicles, has determined that on certain Sprinter (907 platform) vehicles, the routing of the main wiring harness might not meet specifications. In this case, the wiring harness might contact the drive shaft, and chafing over time could result in a short circuit of various wires in the harness. Depending on the affected wire, a risk of fire, loss of propulsion without warning, or failure of the power steering and brake control system cannot be ruled out. As a precautionary measure, an authorized Mercedes-Benz dealer will inspect the routing of the main wiring harness on the affected vehicles and rework it, if necessary.

In this case, the wiring harness might contact the drive shaft, and chafing over time could result in a short circuit of various wires in the harness. Depending on the affected wire, a risk of fire, loss of propulsion without warning, or failure of the power steering and brake control system cannot be ruled out.

Remedy: As a precautionary measure, an authorized Mercedes-Benz dealer will inspect the routing of the main wiring harness on the affected vehicles and rework it, if necessary.

08/30/2024	2,254	California Motor Vehicle Dept. Newcastle, CA		Odometer reading reported
09/19/2024	2,386	Mercedes-Benz of Rocklin Rocklin, CA 916-567-4300 ★ 4.1 / 5.0 284 Verified Reviews ❤️ 5,997 Customer Favorites		Vehicle serviced - Recommended maintenance performed - Air intake hose replaced - Battery replaced - Tire condition and pressure checked - Turbocharger feed line replaced
12/07/2024	2,467	Mercedes-Benz of Rocklin Rocklin, CA 916-567-4300 ★ 4.1 / 5.0 284 Verified Reviews ❤️ 5,997 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Electrical system checked - Tire condition and pressure checked
01/07/2025		California Motor Vehicle Dept. Newcastle, CA		Title issued or updated - First owner reported - Titled or registered as personal vehicle
01/09/2025		Mercedes-Benz of Rocklin Rocklin, CA 916-567-4300 ★ 4.1 / 5.0 284 Verified Reviews ❤️ 5,997 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Engine/powertrain computer/module checked - Tire condition and pressure checked



This vehicle's oil change history, as reported to CARFAX, follows the manufacturer's recommendation. Track your service history for free at carfax.com/service.

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

CARFAX Well Maintained - Regular Oil Changes

CARFAX identifies a "Well Maintained - Regular Oil Change" vehicle as having a regular oil change history when all its recommended oil changes, based on the vehicle's maintenance schedule, have been reported to CARFAX. CARFAX uses the manufacturer's schedule and assumes normal driving conditions. When an oil change schedule is not available, CARFAX may analyze reported service events to determine what is typical for the same make and model vehicle. Dealers and service shops may publish different recommended service schedules.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2025 CARFAX, Inc., part of S&P Global. All rights reserved.
7/7/25 4:29:03 AM (CDT)

